

1/27/2023

| Priority | Calendar Days | Work Order Title | Reported | Priority | Status | Status Date |
|----------|---------------|--|----------|---|--------|-------------|
| 1 | 1 | Housing Signs - Renew signs at 1410/1430 and 1500 Delaware Ave Base Light Poles - Repair INOP street lights as reported during the light round Chapel. Install paper towel dispenser in female head. Chapel. Speaker on bell tower facing the water tower is detaching from the str CDC - Glass window in hallway by infant room has 2 cracks and need replacem CDC - Request outside sign poles at entrance to parking lot be repainted CDC - Request replacement of 13 rusted paper towel dispensers CDC. AC system is INOP and is freezing over. Bldg 251 - Request installation of hand soap dispensers in male and female he 251 - Repair leak at dielectric union on Heating Boiler #1. Bldg 251 - (EOW) Mech Space door needs to be replaced Bldg 252 - Install liquid hand soap dispensers in male and female head Exchange. Emergency Light in the changing room area did not operate upon te Exchange - Roof is leaking on sales floor Exchange - Add new plywood walls/insulation/fan Exchange - Protruding exterior PVC located in rock bed is tripping hazard and n Exchange. Exchange boiler #1 union leaking from gasket Garage - Investigate leaking lines on Mower #5. Maintenance Shop - Install secure box for IT network equipment in lounge. Fire House - Repair/replacement of rotted fence behind bldg Firehouse. Washing machine closest to back door leaking. Fire house - Request outlet to connect washer/dryer Fire house. Ceiling leak in rear bay area near laundry machines. Galley- Missing kick tile by inside door and two cracked kick tiles in walk in by f Galley - Ceiling tiles need to be replaced, mold is starting to grow | INPRG | In progress: The work is actively being done | | |
| 2 | 5 | | APPR | Approved: Job is in the system and is currently being scheduled | | |
| 3 | 20 | | WMATL | Awaiting Materials: Job is in progress, but we are waiting on parts | | |
| 4 | 45 | | WAPPR | Awaiting Approval: Someone will be by to check the issue out, or call | | |
| 5 | 180 | | | | | |
| 6 | 365 | | | | | |

| Location Description | W/O # | Work Order Title | Reported | Priority | Status | Status Date |
|---|----------|---|-----------|----------|--------|-------------|
| CG TRACEN CAPE MAY - OWNED LAND | 17361993 | Housing Signs - Renew signs at 1410/1430 and 1500 Delaware Ave | 3/10/2021 | 4 | WMATL | 8/9/2021 |
| CG Tracen Cape May - Owned Land (Parcel 1 | 23036129 | Base Light Poles - Repair INOP street lights as reported during the light round | 2/24/2023 | 4 | INPRG | 2/24/2023 |
| CHAPEL | 23222588 | Chapel. Install paper towel dispenser in female head. | 3/7/2023 | 4 | INPRG | 3/7/2023 |
| CHAPEL | 20074652 | Chapel. Speaker on bell tower facing the water tower is detaching from the str | 2/18/2022 | 2 | INPRG | 2/22/2022 |
| CHILD DEVELOPMENT CENTER | 21330273 | CDC - Glass window in hallway by infant room has 2 cracks and need replacem | 7/26/2022 | 3 | APPR | 7/27/2022 |
| CHILD DEVELOPMENT CENTER | 21782510 | CDC - Request outside sign poles at entrance to parking lot be repainted | 9/23/2022 | 4 | APPR | 9/23/2022 |
| CHILD DEVELOPMENT CENTER | 22761673 | CDC - Request replacement of 13 rusted paper towel dispensers | 1/13/2023 | 4 | APPR | 1/25/2023 |
| CHILD DEVELOPMENT CENTER | 21303503 | CDC. AC system is INOP and is freezing over. | 7/15/2022 | 2 | INPRG | 7/15/2022 |
| CLASSROOM-251 | 22760435 | Bldg 251 - Request installation of hand soap dispensers in male and female he | 1/11/2023 | 4 | APPR | 1/20/2023 |
| CLASSROOM-251 | 18106519 | 251 - Repair leak at dielectric union on Heating Boiler #1. | 6/9/2021 | 4 | APPR | 6/9/2021 |
| CLASSROOM-251 | 22283123 | Bldg 251 - (EOW) Mech Space door needs to be replaced | 11/8/2022 | 4 | APPR | 11/14/2022 |
| CLASSROOM-252 | 22760436 | Bldg 252 - Install liquid hand soap dispensers in male and female head | 1/11/2023 | 4 | APPR | 1/20/2023 |
| EXCHANGE | 22803937 | Exchange. Emergency Light in the changing room area did not operate upon te | 1/30/2023 | 2 | INPRG | 1/30/2023 |
| EXCHANGE | 22512116 | Exchange - Roof is leaking on sales floor | 12/6/2022 | 2 | APPR | 12/8/2022 |
| EXCHANGE | 20551813 | Exchange - Add new plywood walls/insulation/fan | 4/12/2022 | 4 | WMATL | 8/1/2022 |
| EXCHANGE | 19791899 | Exchange - Protruding exterior PVC located in rock bed is tripping hazard and n | 1/7/2022 | 4 | APPR | 1/10/2022 |
| EXCHANGE | 23005644 | Exchange. Exchange boiler #1 union leaking from gasket | 2/9/2023 | 2 | INPRG | 2/16/2023 |
| FE CENTRAL SUPPLY | 22773146 | Garage - Investigate leaking lines on Mower #5. | 1/26/2023 | 3 | INPRG | 1/26/2023 |
| FE MAINTENANCE/STORAGE | 21548523 | Maintenance Shop - Install secure box for IT network equipment in lounge. | 8/22/2022 | 4 | WMATL | 8/23/2022 |
| FIRE HOUSE | 18806826 | Fire House - Repair/replacement of rotted fence behind bldg | 9/2/2021 | 5 | INPRG | 10/26/2022 |
| FIRE HOUSE | 23009846 | Firehouse. Washing machine closest to back door leaking. | 2/13/2023 | 4 | APPR | 2/13/2023 |
| FIRE HOUSE | 22284082 | Fire house - Request outlet to connect washer/dryer | 11/9/2022 | 4 | INPRG | 1/30/2023 |
| FIRE HOUSE | 23009657 | Fire house. Ceiling leak in rear bay area near laundry machines. | 2/13/2023 | 2 | APPR | 2/13/2023 |
| GALLEY | 16144518 | Galley- Missing kick tile by inside door and two cracked kick tiles in walk in by f | 10/8/2020 | 3 | WMATL | 11/18/2020 |
| GALLEY | 21540435 | Galley - Ceiling tiles need to be replaced, mold is starting to grow | 8/16/2022 | 4 | APPR | 8/17/2022 |

LEGEND

In progress: The work is actively being done
 Approved: Job is in the system and is currently being scheduled
 Awaiting Materials: Job is in progress, but we are waiting on parts
 Awaiting Approval: Someone will be by to check the issue out, or call

| | | | | | | |
|-----------------------------|----------|---|------------|---|-------|------------|
| GALLEY | 23013894 | Galley. Galley vents need to be serviced/cleaned | 2/14/2023 | 3 | APPR | 2/15/2023 |
| GALLEY | 23013896 | Galley. Rational oven Keeps aborting clean cycle.. | 2/14/2023 | 2 | INPRG | 2/15/2023 |
| GALLEY | 22308544 | Galley - leaking pipes in PP side dish room | 11/25/2022 | 2 | INPRG | 11/29/2022 |
| GALLEY | 21778823 | Galley. AC is INOP on the perm party side mess deck. | 9/19/2022 | 2 | APPR | 9/19/2022 |
| GALLEY | 21508058 | Galley - Mold on ceiling tiles in shift leader office/dry stores | 8/8/2022 | 2 | APPR | 8/8/2022 |
| GALLEY | 19634425 | Galley - Freezer breakout - LEDs | 12/27/2021 | 4 | INPRG | 1/13/2022 |
| GALLEY | 23214807 | Galley. Port side dishwasher not keeping up to temp. | 3/6/2023 | 2 | INPRG | 3/6/2023 |
| GALLEY | 21988301 | Galley - 60 AT mixer bowl will not work properly | 10/6/2022 | 3 | WMATL | 10/7/2022 |
| GALLEY | 22660040 | Galley. Port side steam line will not heat up. | 1/3/2023 | 2 | INPRG | 1/4/2023 |
| GALLEY | 22334203 | Galley - Dish machine not hot enough for dishwashing temps, also machine leak | 11/28/2022 | 2 | INPRG | 11/29/2022 |
| GALLEY | 23024463 | Galley. Remove existing CO2 bottle storage container on loading dock and aff | 2/21/2023 | 3 | INPRG | 3/6/2023 |
| GALLEY | 20061694 | Galley - Outside air dampners on AHU-4 INOP. | 2/10/2022 | 6 | INPRG | 2/11/2022 |
| GALLEY | 23026266 | Goff Hall- install eye wash station-- Mech room | 2/22/2023 | 3 | INPRG | 2/24/2023 |
| GOFF HALL | 19097109 | Goff Hall - Chipped flooring in front of the fire trainer | 10/19/2021 | 5 | APPR | 10/20/2021 |
| GOFF HALL | 21766912 | Garage - Kubota L3240 will not start. | 9/8/2022 | 3 | INPRG | 9/8/2022 |
| GOFF HALL | 23201339 | Garage - Replace headlights on Kubota L3240 tractor. | 3/1/2023 | 4 | INPRG | 3/2/2023 |
| GYMNASIUM - FITNESS CENTER | 22548477 | Gym - Pool deck HVAC ducting needs cleaning (interior) | 12/21/2022 | 5 | APPR | 12/22/2022 |
| GYMNASIUM - FITNESS CENTER | 19791924 | Gym - Repair cracked concrete above lower level stairwell | 1/7/2022 | 5 | APPR | 1/10/2022 |
| GYMNASIUM - FITNESS CENTER | 15254816 | GYM - Request window in pool area be tinted | 6/26/2020 | 4 | WMATL | 8/9/2021 |
| GYMNASIUM - FITNESS CENTER | 19792512 | Gym - Replace metal piece of 3rd stair from bottom (on stairs going down to p | 1/7/2022 | 5 | WMATL | 1/10/2022 |
| GYMNASIUM - FITNESS CENTER | 22545846 | Gym - Mount clothes dryer/make cord | 12/19/2022 | 3 | APPR | 12/20/2022 |
| GYMNASIUM - FITNESS CENTER | 19791910 | Gym - Concrete ceiling above hot water return in lower level needs to be patch | 1/7/2022 | 5 | APPR | 1/10/2022 |
| GYMNASIUM - FITNESS CENTER | 19791925 | Gym - Tile between toilet area and sink in male head needs to be repaired | 1/7/2022 | 5 | APPR | 1/10/2022 |
| HARBORVIEW COMMUNITY CLUB | 22768792 | Harborview - Remove bugs from lights in main dining room | 1/25/2023 | 4 | INPRG | 2/3/2023 |
| HARBORVIEW COMMUNITY CLUB | 19433116 | Harborview - Water main is severely rusted and corroded | 11/30/2021 | 4 | WMATL | 12/1/2021 |
| HAZARDOUS STORAGE FACILITY | 22025396 | HAZ Yard - Replace doors at room A&B due to heavy corrosion | 10/25/2022 | 4 | APPR | 10/26/2022 |
| HEALY HALL BARRACKS | 20089781 | Healy - Mold in 2W ceiling | 2/23/2022 | 2 | APPR | 2/23/2022 |
| HEALY HALL BARRACKS | 21958154 | Healy - Squad bay door glass is cracked in 2W | 10/4/2022 | 2 | APPR | 10/4/2022 |
| HEALY HALL BARRACKS | 20090179 | Healy - Mold in 2N ceiling | 2/23/2022 | 2 | APPR | 2/23/2022 |
| HEALY HALL BARRACKS | 20582355 | Healy- ceiling leak above light, drywall falling 2ST head | 4/21/2022 | 2 | INPRG | 4/21/2022 |
| HEALY HALL BARRACKS | 23026263 | Healy Hall - 1 West Squadbay Head flooring and shower ceiling. | 2/13/2023 | 4 | INPRG | 2/13/2023 |
| HEALY HALL BARRACKS | 23202612 | Healy Hall. Repair flooring in head of 3N squad bay. | 3/2/2023 | 4 | APPR | 3/2/2023 |
| HEALY HALL BARRACKS | 21736812 | Healy - ceiling leak in the air handler system causing air handler to be filled wit | 9/6/2022 | 2 | INPRG | 9/7/2022 |
| HEALY HALL BARRACKS | 22840168 | Healy - Troubleshoot and map out exhaust system for building. | 1/27/2023 | 4 | INPRG | 1/27/2023 |
| HEALY HALL BARRACKS | 22740731 | Healy - Soap dispensers are not working properly | 1/6/2023 | 3 | WMATL | 1/10/2023 |
| HEALY HALL BARRACKS | 21531608 | Healy - Replace damaged or missing covers / louvers on Samsung units. | 8/15/2022 | 5 | INPRG | 9/12/2022 |
| IDA LEWIS THEATER/WORK-LIFE | 22472277 | Ida Lewis - Stucco is falling off section of building on ramp | 12/1/2022 | 4 | INPRG | 12/19/2022 |

| | | | | | | |
|-------------------------------------|----------|---|------------|---|-------|------------|
| IDA LEWIS THEATER/WORK-LIFE | 22504685 | Ida Lewis - Water leak in male head from fire suppression system | 12/5/2022 | 1 | INPRG | 12/6/2022 |
| JAMES HALL BARRACKS | 21753300 | James - Leak in ceiling dripping onto light fixture in 1 North Squadbay. | 9/7/2022 | 2 | INPRG | 9/7/2022 |
| JAMES HALL BARRACKS | 23233185 | James Hall. Multiple toilet issues on 01 deck squad bays. | 3/7/2023 | 3 | INPRG | 3/7/2023 |
| JAMES HALL BARRACKS | 22006481 | James - Fan motor bearing has a rattle. | 10/13/2022 | 3 | INPRG | 10/19/2022 |
| JAMES HALL BARRACKS | 22742895 | Fire house. Numerous trouble alarms, Open circuit, B258 James Hall Bell Ckt. | 1/9/2023 | 2 | INPRG | 1/9/2023 |
| LAUNDRY | 19793775 | Laundry - Insulation around all dryer vent pipes is degraded. Re-tape/insulate | 1/7/2022 | 5 | APPR | 1/10/2022 |
| MAIN GATE HOUSE | 23203104 | Front Gate arm stuck open | 3/2/2023 | 3 | INPRG | 3/2/2023 |
| MAIN GATE HOUSE | 23013893 | Security. front gate arm has been malfunctioning. The arm gate will go up and | 2/14/2023 | 2 | APPR | 2/15/2023 |
| MCPO 911 CLASSROOMS | 20815755 | 911 - Outside Air damper control system INOP. | 5/20/2022 | 3 | INPRG | 5/23/2022 |
| MEDICAL-DENTAL BUILDING | 19796501 | Medical - Replace unit heater motors. | 1/10/2022 | 4 | WMATL | 3/23/2022 |
| MEDICAL-DENTAL BUILDING | 22742139 | Medical - Multiple lightbulbs near entrances to building are out | 1/6/2023 | 3 | INPRG | 1/9/2023 |
| MEDICAL-DENTAL BUILDING | 20544839 | Medical - Pressure reducing valve has failed. | 3/24/2022 | 3 | WMATL | 3/25/2022 |
| MEDICAL-DENTAL BUILDING | 18436923 | Medical - Request deadbolt to secure door to Med boards and Physical Exams | 7/29/2021 | 5 | APPR | 7/30/2021 |
| MEDICAL-DENTAL BUILDING | 17822529 | Medical - Chill water pump #2 is leaking at solder connection on vertical pipe in | 5/4/2021 | 3 | APPR | 5/5/2021 |
| MISSION SUPPORT BLDG | 22875775 | Mission Support. Left side urinal in recruit head has a constant running water r | 2/1/2023 | 2 | INPRG | 2/2/2023 |
| MISSION SUPPORT BLDG | 21511689 | Mission Support Bldg - Remove/replace waterless urinal by legal/public affairs | 8/9/2022 | 5 | WMATL | 1/26/2023 |
| MISSION SUPPORT BLDG | 23222941 | Mission Support - FCU in FE is blowing cold air | 3/7/2023 | 3 | INPRG | 3/7/2023 |
| MISSION SUPPORT BLDG | 21782580 | Multi-Mission Bldg - Leak/damp puddle appears at floor/wall intersect after he | 9/23/2022 | 3 | INPRG | 9/23/2022 |
| MISSION SUPPORT BLDG | 21520194 | Multi-Mission Bldg - Leak in SBT Offices | 8/11/2022 | 2 | INPRG | 8/23/2022 |
| MULTI-MISSION BUILDING | 22303664 | Multi-Mission Bldg - No heat in room 237 | 11/21/2022 | 1 | APPR | 11/21/2022 |
| MULTI-MISSION BUILDING | 21782323 | Multi-Mission Bldg - VBST storage room has mold issues | 9/22/2022 | 3 | APPR | 9/28/2022 |
| MUNRO HALL | 23233982 | Munro - Exterior fire alarm horn/strobe combo unit INOP. | 3/7/2023 | 2 | INPRG | 3/7/2023 |
| MUNRO HALL | 23230700 | Munro - leaking around manhole covers out front with sewage odor | 3/7/2023 | 1 | INPRG | 3/7/2023 |
| OCEANSIDE COMMUNITY CLUB | 22016991 | Oceanside. Water fountain leaking. | 10/19/2022 | 2 | INPRG | 10/19/2022 |
| OCEANSIDE COMMUNITY CLUB | 21251615 | Oceanside - Middle urinal does not flush properly and runs water for a long pe | 7/6/2022 | 2 | INPRG | 7/28/2022 |
| OCEANSIDE COMMUNITY CLUB | 21757608 | Oceanside - 2 of 3 urinals are not operating | 9/8/2022 | 2 | INPRG | 9/12/2022 |
| OCEANSIDE COMMUNITY CLUB | 20376442 | Oceanside. Repair (2) broken window levers in dining area | 3/29/2022 | 4 | INPRG | 4/18/2022 |
| OCEANSIDE COMMUNITY CLUB | 22749850 | Oceanside - toilet continues to run and urinal valves malfunctioning | 1/10/2023 | 4 | APPR | 1/10/2023 |
| PIER FOUR | 21837987 | Pier 4 - Fire extinguisher boxes along piers have been rusted out and need rep | 9/30/2022 | 4 | APPR | 10/4/2022 |
| RANGE AMMO | 23222587 | Bunker Bldg 202. Replace broken exterior fire extinguisher case. | 3/7/2023 | 3 | APPR | 3/7/2023 |
| RECRUIT TRANSIENT BARRACKS-BLDG 303 | 23222035 | Sexton - Water heater showing a fault code. | 3/6/2023 | 2 | WMATL | 3/7/2023 |
| RECRUIT TRANSIENT BARRACKS-BLDG 303 | 15203742 | Sexton Hall - Shower handle faceplate has come loose | 6/12/2020 | 6 | WMATL | 9/11/2020 |
| RECRUIT TRANSIENT BARRACKS-BLDG 303 | 22305733 | Sexton - Numerous floor tiles throughout building are loose or cracked | 11/22/2022 | 4 | INPRG | 12/6/2022 |
| RECRUIT TRANSIENT BARRACKS-BLDG 303 | 17597846 | Sexton Hall. Showers in 108 #7&8 handles stuck, #11&12 low pressure and col | 4/8/2021 | 3 | INPRG | 4/9/2021 |

| | | | | | | |
|--------------------------------|----------|---|------------|---|-------|------------|
| ROADS | 22741731 | Exchange generator area, sink hole | 1/6/2023 | 4 | INPRG | 1/9/2023 |
| ROADS | 22016986 | Roads. repair sink hole at the corner of Virginia and Perchard | 10/19/2022 | 4 | APPR | 10/24/2022 |
| ROADS | 20332689 | Request stop line be painted by old luckybag across from bulk dumpsters | 3/24/2022 | 4 | APPR | 3/24/2022 |
| ROADS | 22016987 | Roads. repair sink hole at the corner of Diligence Ave and Buffalo Ave at water | 10/19/2022 | 4 | APPR | 10/24/2022 |
| ROADS | 16908736 | Request to add 03 stop signs behind Admin, between admin and garage | 1/21/2021 | 5 | WMATL | 9/9/2021 |
| ROADS | 20360958 | Roads - Paint a stop line at GSK at stop sign leading out to Munro | 3/28/2022 | 4 | APPR | 3/29/2022 |
| RUNNING TRACK | 23123669 | Diesel powered light tower not working | 3/1/2023 | 4 | INPRG | 3/1/2023 |
| SANITARY SEWAGE SYSTEM | 22401939 | Sanitary Sewer - Sewer is clogged between Medical and the Galley. | 11/29/2022 | 2 | INPRG | 11/29/2022 |
| SEAMANSHP TRAINING BUILDING | 22020716 | B. Webber/Seamanship flooring project | 10/21/2022 | 6 | APPR | 10/24/2022 |
| SEAMANSHP TRAINING BUILDING | 20091458 | Seamanship - Replace heat exchanger on boiler #1. | 2/24/2022 | 4 | WMATL | 2/25/2022 |
| SEAMANSHP TRAINING BUILDING | 19089469 | Repair 1-step flooring at threshold of door into instructor lounge from lobby | 10/19/2021 | 5 | APPR | 10/19/2021 |
| SECURITY BUILDING | 23206526 | Security. Water leaking from roof in breakroom. | 3/3/2023 | 3 | INPRG | 3/6/2023 |
| SHIPPING & RECEIVING | 21256090 | GSK (post office) - Label post office exterior entrance | 7/6/2022 | 4 | APPR | 7/13/2022 |
| SIDEWALKS | 19190614 | Sidewalks - Repair various sidewalk sections on base | 11/1/2021 | 4 | APPR | 11/1/2021 |
| SIDEWALKS | 20786979 | Repair cement slab around manhole cover outside of the recruit entrance to g | 5/10/2022 | 3 | APPR | 5/10/2022 |
| STATION CAPE MAY BOAT STORAGE | 22216354 | Boat House - Lighting in south end storage space not working. | 11/1/2022 | 3 | INPRG | 11/3/2022 |
| STATION CAPE MAY BOAT STORAGE | 21054865 | Boat House - Replace exhaust fan motor for EF-4. | 6/15/2022 | 4 | WMATL | 6/15/2022 |
| STREET LIGHTS BASE-HSG | 22997266 | Munro ave & Perchard streetlight extinguished. | 2/7/2023 | 3 | INPRG | 2/13/2023 |
| STREET LIGHTS BASE-HSG | 23036127 | Housing Light Poles - Lights 64, 65 and 68 found INOP during light round PM or | 2/24/2023 | 4 | INPRG | 2/24/2023 |
| SUN SHADE 2 @ PLAYGROUND #4 | 17364454 | Sunshade at big playground in 1500 block - Canopy is missing | 3/10/2021 | 5 | WMATL | 3/23/2022 |
| TRANSIENT HOUSING 283 | 23234095 | BLDG 283 - All three toilets are clogged and the sewer main is possibly clogged | 3/7/2023 | 2 | INPRG | 3/7/2023 |
| TRANSIENT HOUSING 287 | 22764055 | Temp Housing 287-B - CO detector #23 is coming in the Siemens panel as input | 1/17/2023 | 2 | WMATL | 1/20/2023 |
| TRANSIENT HOUSING 288 | 22749142 | Temp Quarters 288 - Trouble alarm showing on Fire House Alarm Panel. | 1/9/2023 | 3 | WMATL | 1/9/2023 |
| UNIFORM DIST CTR (UDC) DEMPSEY | 22545324 | UDC - Add 5 smoke detectors to existing fire alarm system | 12/16/2022 | 4 | INPRG | 2/13/2023 |
| UNIFORM DIST CTR (UDC) DEMPSEY | 22773473 | UDC (Tailor shop) - Request door be installed in tailor shop fitting room | 1/26/2023 | 4 | INPRG | 1/30/2023 |
| UNIFORM DIST CTR (UDC) DEMPSEY | 21834224 | UDC - Adjust louvers so they do not blow straight down | 9/30/2022 | 4 | APPR | 10/12/2022 |
| UNIFORM DIST CTR (UDC) DEMPSEY | 23214799 | UDC. Exterior door to the tailor shop is not working properly. | 3/6/2023 | 3 | INPRG | 3/6/2023 |
| UNIFORM DIST CTR (UDC) DEMPSEY | 22761683 | UDC - Request 1 or 2 handicap spots | 1/13/2023 | 3 | APPR | 2/27/2023 |
| UNPAVED ROADS (ALL) | 22734058 | Roads - Regrade the back roads | 1/6/2023 | 4 | INPRG | 1/9/2023 |
| UPH BUILDING 254 | 23207883 | UPH Panic alarm system problem | 3/3/2023 | 3 | INPRG | 3/6/2023 |
| VIP GRANDSTAND @ PARADE | 16155401 | Parade field - Replace all speaker brackets on audio poles | 10/14/2020 | 4 | WMATL | 4/7/2021 |