

As of 11/17/2021 @ 1020

Priority

Calendar Days

1

1

2

5

3

20

4

45

5

180

6

365

Please note: Your work order has been assigned a priority, which corresponds with a number of days in which the work must be completed. Please call 609-898-6945 with any further questions.

LEGEND

INPRG

In progress: The work is actively being done

APPR

Approved: Job is in the system and is currently being scheduled

WMATL

Awaiting Materials: Job is in progress, but we are waiting on parts

WAPPR

Awaiting Approval: Someone will be by to check the issue out, or call

Location Description

W/O #

Work Order Title

Reported

Priority

Status

Status Date

1724 Pennsylvania Avenue Unit D	18839730	P-1724-D Kitchen flooring is in the poor condition with slit m	9/13/2021	5	APPR	9/14/2021
1521 Pennsylvania Avenue Unit F	18857534	P-1521-F. AC is not working properly.	9/20/2021	2	WMATL	10/12/2021
1741 Pennsylvania Avenue Unit D	18857538	P-1741-D. Light in stairwell needs to be replaced.	9/20/2021	3	APPR	9/20/2021
HOUSING MAINTENANCE SHOP (SELF HELP)	18928869	Housing Maintenance - Inspect/purchase all equipment/mat	9/30/2021	4	APPR	9/30/2021
HOUSING MAINTENANCE SHOP @290	18929239	Housing Maintenance Shop - Inspect and purchase all equipm	9/30/2021	4	APPR	9/30/2021
SIDEWALKS	18929244	Sidewalks - Inspect and purchase all materials needed to repa	9/30/2021	4	APPR	9/30/2021
SKATE PARK	18929245	Skate Park - Inspect/purchase all equipment and materials ne	9/30/2021	4	APPR	9/30/2021
CAPTAINS QUARTERS	19064983	Quarters "A" Mailbox paint is coming off	10/7/2021	4	APPR	10/12/2021
STREET LIGHTS BASE-HSG	19064996	Street lights in housing - The base of some of the lights is corr	10/7/2021	4	WMATL	10/22/2021
1750 Delaware Avenue Unit A	19080326	D-1750-A Child lock on washing machine is not working/mild	10/14/2021	3	APPR	10/14/2021
1840 Pennsylvania Avenue Unit B	19080325	P-1840-B Dryer vent screen is off/missing	10/14/2021	3	APPR	10/14/2021
1812 Pennsylvania Avenue Unit C	19081075	P-1812-C Refrigerator door is broke and door will not close p	10/18/2021	2	APPR	10/18/2021
1812 Pennsylvania Avenue Unit C	19081070	P-1812-C Request pest services for animal/rodent in wall	10/18/2021	2	APPR	10/18/2021
1521 Pennsylvania Avenue Unit C	19097146	P-1521-C Fence in back yard is coming down (Annual Inspect	10/19/2021	4	APPR	10/20/2021
FE/VESSEL STORAGE	19099256	Bunker storage (Bldg 196) - Mark all gear stored in the bunke	10/20/2021	4	APPR	10/20/2021
1831 PENNSYLVANIA AVENUE	19105341	P-1831 Request removal of all window A/C units	10/25/2021	4	APPR	10/26/2021
1741 Pennsylvania Avenue Unit A	19109581	P-1741-A Dishwasher is not draining and leaking while runnir	10/26/2021	3	APPR	10/26/2021
1421 Pennsylvania Avenue Unit B	19123185	P-1421-B refrigerator squealing noise	10/27/2021	3	APPR	10/27/2021
1611 Pennsylvania Avenue Unit C	19131922	P-1611-C Oven knob broke off	10/28/2021	3	APPR	10/28/2021
1500 Delaware Avenue Unit B	19183065	D-1500-B Dishwasher leaking	11/1/2021	3	APPR	11/1/2021
1520 Delaware Avenue Unit A	19249312	D-1520-A Kitchen drawer face is loose (Annual Inspection)	11/1/2021	4	APPR	11/2/2021

1611 Pennsylvania Avenue Unit E	19226250	P-1611-E Dishwasher randomly stops working mid-cycle	11/1/2021	3	APPR	11/1/2021
1750 Pennsylvania Avenue Unit C	19242425	P-1750-C Dishwasher is not working, bottom piece melted	11/1/2021	3	APPR	11/1/2021
1611 Pennsylvania Avenue Unit A	19272009	P-1611-A No heat	11/2/2021	1	APPR	11/3/2021
1540 Delaware Avenue Unit A	19273413	D-1540-A Small amount of water is leaking from hot water h	11/3/2021	2	APPR	11/3/2021
1540 Delaware Avenue Unit A	19273651	D-1540-A Back yard fence wood plank is extremely loose	11/3/2021	4	APPR	11/4/2021
1560 Delaware Avenue Unit A	19286284	D-1560-A Toilet is running in bathroom	11/3/2021	2	APPR	11/4/2021
1560 Delaware Avenue Unit A	19286285	D-1560-A Back screen door is torn, bottom panel front door	11/3/2021	4	APPR	11/4/2021
1750 Delaware Avenue Unit A	19274626	D-1750-A Request removal/storage of 3 bifold doors	11/3/2021	4	APPR	11/4/2021
1750 Delaware Avenue Unit B	19274655	D-1750-B Request to have broken trash and recycling can rep	11/3/2021	4	APPR	11/4/2021
1500 Delaware Avenue Unit F	19301285	D-1500-F Downstairs bathroom fan is making a really loud no	11/5/2021	3	APPR	11/8/2021
1520 Delaware Avenue Unit A	19301312	D-1520-A Cabinet over toilet fell off the wall	11/5/2021	4	APPR	11/8/2021
1710 Delaware Avenue Unit B	19301005	D-1710-B There is a crack in the shower wall	11/5/2021	3	APPR	11/8/2021
1710 Delaware Avenue Unit B	19301000	D-1710-B Upstairs 2 bedrooms have wetness in the corners c	11/5/2021	2	APPR	11/8/2021
1710 Delaware Avenue Unit B	19301004	D-1710-B Outlet is coming out of wall	11/5/2021	4	APPR	11/8/2021
1710 Delaware Avenue Unit B	19301007	D-1710-B Missing blue recycle bin	11/5/2021	4	APPR	11/8/2021
1710 Delaware Avenue Unit B	19301002	D-1710-B Dishwasher leaks water - maybe a gasket fix	11/5/2021	3	APPR	11/8/2021
1826 Pennsylvania Avenue Unit B	19301289	P-1826-B Mold growing on wall next go bathtub and on vent	11/5/2021	2	APPR	11/8/2021
1410 A/B/C/D DELAWARE AVENUE	19309002	1410 A/B/C/D Assess condenser platforms for structural stab	11/9/2021	5	APPR	11/10/2021
1421 A/B/C/D PENNSYLVANIA AVENUE	19309012	1421 A/B/C/D Assess condenser platforms for structural stab	11/9/2021	5	APPR	11/10/2021
1430 A/B/C/D DELAWARE AVENUE	19309007	1430 A/B/C/D Assess condenser platforms for structural stab	11/9/2021	5	APPR	11/10/2021
1431 A/B/C/D PENNSYLVANIA AVENUE	19309014	1431 A/B/C/D Assess condenser platforms for structural stab	11/9/2021	5	APPR	11/10/2021
1441 A/B/C/D PENNSYLVANIA AVENUE	19309015	1441 A/B/C/D Assess condenser platforms for structural stab	11/9/2021	5	APPR	11/10/2021
1450 A/B/C/D DELAWARE AVENUE	19309009	1450 A/B/C/D Assess condenser platforms for structural stab	11/9/2021	5	APPR	11/10/2021
1460 A/B/C/D DELAWARE AVENUE	19309011	1460 A/B/C/D Assess condenser platforms for structural stab	11/9/2021	5	APPR	11/10/2021
1461 A/B/C/D PENNSYLVANIA AVENUE	19309216	1461 A/B/C/D Assess condenser platforms for structural stab	11/9/2021	5	APPR	11/10/2021
1500 A/B/C/D/E/F DELAWARE AVENUE	19309230	1500 A/B/C/D/E/F Assess condenser platforms for structural :	11/9/2021	5	APPR	11/10/2021
1501 A/B/C/D/E PENNSYLVANIA AVENUE	19309406	1501 A/B/C/D/E Assess condenser platforms for structural sta	11/9/2021	5	APPR	11/10/2021
1520 A/B/C/D/E DELAWARE AVENUE	19309402	1520 A/B/C/D/E Assess condenser platforms for structural sta	11/9/2021	5	APPR	11/10/2021
1521 A/B/C/D/E/F PENNSYLVANIA AVENUE	19309410	1521 A/B/C/D/E/F Assess condenser platforms for structural :	11/9/2021	5	APPR	11/10/2021
1540 A/B/C/D/E DELAWARE AVENUE	19309403	1540 A/B/C/D/E Assess condenser platforms for structural sta	11/9/2021	5	APPR	11/10/2021
1540 Delaware Avenue Unit B	19312327	D-1540-B Small section of siding came off	11/9/2021	4	APPR	11/10/2021
1541 A/B/C/D PENNSYLVANIA AVENUE	19309843	1541 A/B/C/D Assess condenser platforms for structural stab	11/9/2021	5	APPR	11/10/2021
1541 Pennstlvania Avenue Unit C	19309229	P-1541-C Bathtub is not draining	11/9/2021	2	APPR	11/10/2021
1560 A/B/C/D DELAWARE AVENUE	19309405	1560 A/B/C/D Assess condenser platforms for structural stab	11/9/2021	5	APPR	11/10/2021

1561 A/B/C/D/E PENNSYLVANIA AVENUE	19310018	1561 A/B/C/D/E Assess condenser platforms for structural sta	11/9/2021	5 APPR	11/10/2021
1611 A/B/C/D/E PENNSYLVANIA AVENUE	19309222	1611 A/B/C/D/E Assess condenser platforms for structural sta	11/9/2021	5 APPR	11/10/2021
1651 A/B/C/D/E PENNSYLVANIA AVENUE	19309226	1651 A/B/C/D/E Assess condenser platforms for structural sta	11/9/2021	5 APPR	11/10/2021
1651 Pennsylvania Avenue Unit A	19309019	P-1651-A Bottom rack on dishwasher is rusted and staining d	11/9/2021	3 APPR	11/10/2021
1651 Pennsylvania Avenue Unit E	19308994	P-1651-E Dishwasher is leaking when running	11/9/2021	3 APPR	11/15/2021
1710 A/B/C/D DELAWARE AVENUE	19311343	1710 A/B/C/D Assess condenser platforms for structural stabi	11/9/2021	5 APPR	11/10/2021
1720 A/B/C/D DELAWARE AVENUE	19311348	1720 (Delaware) A/B/C/D Assess condenser platforms for stru	11/9/2021	5 APPR	11/10/2021
1720 A/B/C/D PENNSYLVANIA AVENUE	19311866	1720 (Pennsylvania) A/B/C/D Assess condenser platforms for	11/9/2021	5 APPR	11/10/2021
1724 A/B/C/D PENNSYLVANIA AVENUE	19312341	1724 A/B/C/D Assess condenser platforms for structural stabi	11/9/2021	5 APPR	11/10/2021
1730 A/B/C/D PENNSYLVANIA AVENUE	19312342	1730 A/B/C/D Assess condenser platforms for structural stabi	11/9/2021	5 APPR	11/10/2021
1734 A/B/C/D PENNSYLVANIA AVENUE	19312345	1734 A/B/C/D Assess condenser platforms for structural stabi	11/9/2021	5 APPR	11/10/2021
1740 A/B/C/D DELWARE AVENUE	19311353	1740 A/B/C/D Assess condenser platforms for structural stabi	11/9/2021	5 APPR	11/10/2021
1750 A/B/C/D DELAWARE AVENUE	19311356	1750 (Delaware) A/B/C/D Assess condenser platforms for stru	11/9/2021	5 APPR	11/10/2021
1750 A/B/C/D PENNSYLVANIA AVENUE	19312483	1750 (Pennsylvania) A/B/C/D Assess condenser platforms for	11/9/2021	5 APPR	11/10/2021
1754 A/B/C/D PENNSYLVANIA AVENUE	19312493	1754 A/B/C/D Assess condenser platforms for structural stabi	11/9/2021	5 APPR	11/10/2021
1800 A/B/C/D DELAWARE AVENUE	19309217	1800 A/B/C/D Assess condenser platforms for structural stabi	11/9/2021	5 APPR	11/10/2021
1801 A/B/C/D PENNSYLVANIA AVENUE - HS	19309220	1801 A/B/C/D Assess condenser platforms for structural stabi	11/9/2021	5 APPR	11/10/2021
1810 A/B/C/D PENNSYLVANIA AVENUE	19309218	1810 A/B/C/D Assess condenser platforms for structural stabi	11/9/2021	5 APPR	11/10/2021
1812 A/B/C/D PENNSYLVANIA AVENUE	19309221	1812 A/B/C/D Assess condenser platforms for structural stabi	11/9/2021	5 APPR	11/10/2021
1711 Pennsylvania Avenue Unit D	19313800	P-1711-D Both CO detectors are expired and do not work	11/10/2021	1 APPR	11/10/2021
1760 A/B/C/D PENNSYLVANIA AVENUE	19313947	1760 A/B/C/D Assess condenser platforms for structural stabi	11/10/2021	5 APPR	11/10/2021
1824 A/B PENNSYLVANIA AVENUE	19313971	1824 A/C Assess condenser platforms for structural stability a	11/10/2021	5 APPR	11/10/2021
1826 A/B PENNSYLVANIA AVENUE	19313972	1826 A/B Assess condenser platforms for structural stability a	11/10/2021	5 APPR	11/10/2021
1711 A/B/C/D PENNSYLVANIA AVENUE	19316942	1711 A/B/C/D Assess condenser platforms for structural stabi	11/12/2021	5 APPR	11/12/2021
1724 Pennsylvania Avenue Unit C	19316561	P-1724-C Ceiling is starting to crack/crumble, Tub surround is	11/12/2021	3 APPR	11/12/2021
1724 Pennsylvania Avenue Unit C	19316557	P-1724-C Mold around upstairs bathroom fan and	11/12/2021	2 APPR	11/12/2021
1724 Pennsylvania Avenue Unit C	19316560	P-1724-C Circuit breaker randomly makes buzzing noise, ceili	11/12/2021	3 APPR	11/12/2021
1730 Pennsylvania Avenue Unit C	19316542	P-1730-C Possible black mold when heat is on	11/12/2021	2 APPR	11/12/2021
1730 Pennsylvania Avenue Unit C	19316537	P-1730-C Dishwasher is still not working, does not dry dishes	11/12/2021	3 APPR	11/12/2021
1730 Pennsylvania Avenue Unit C	19316540	P-1730-C Upstairs toilet doesn't have much water in bowl	11/12/2021	2 APPR	11/12/2021
1731 A/B/C/D PENNSYLVANIA AVENUE	19316941	1731 A/B/C/D Assess condenser platforms for structural stabi	11/12/2021	5 APPR	11/12/2021

1741 A/B/C/D PENNSYLVANIA AVENUE	19316934	1741 A/B/C/D Assess condenser platforms for structural stability	11/12/2021	5	APPR	11/12/2021
1750 Delaware Avenue Unit B	19316874	D-1750-B Request to have exhaust flapper for stove looked at	11/12/2021	4	APPR	11/12/2021
1761 A/B/C/D PENNSYLVANIA AVENUE	19316930	1761 A/B/C/D Assess condenser platforms for structural stability	11/12/2021	5	APPR	11/12/2021
1820 DELAWARE AVENUE	19316880	D-1820 Shower in master bedroom knob is stuck and not working	11/12/2021	3	APPR	11/12/2021
1830 A/B PENNSYLVANIA AVENUE	19316943	1830 A/B Assess condenser platforms for structural stability	11/12/2021	5	APPR	11/12/2021
1834 A/B PENNSYLVANIA AVENUE	19316944	1834 A/B Assess condenser platforms for structural stability	11/12/2021	5	APPR	11/12/2021
1840 A/B PENNSYLVANIA AVENUE	19316945	1840 A/B Assess condenser platforms for structural stability	11/12/2021	5	APPR	11/12/2021
1410 Delaware Avenue Unit B	19320891	D-1410-B Washing machine overflow, water clean up	11/15/2021	2	APPR	11/15/2021
1450 Delaware Avenue Unit C	19320908	D-1450-C no heat in unit	11/15/2021	2	APPR	11/15/2021
1460 Delaware Avenue Unit C	19318325	D-1460-C Oven light bulb is broken and cannot be removed	11/15/2021	2	APPR	11/15/2021
1500 Delaware Avenue Unit E	19320855	D-1500-E CO detector end of life, replace	11/15/2021	2	APPR	11/15/2021
1501 Pennsylvania Avenue Unit B	19320915	P-1501-B upstairs tub not draining	11/15/2021	2	APPR	11/15/2021
1520 Delaware Avenue Unit D	19320856	D-1520-D no heat	11/15/2021	2	APPR	11/15/2021
1540 Delaware Avenue Unit A	19319652	D-1540-A CO detector end of life, replace	11/15/2021	2	APPR	11/15/2021
1560 Delaware Avenue Unit C	19319509	D-1560-C CO detector end of life, replace	11/15/2021	2	APPR	11/15/2021
1561 Pennsylvania Avenue Unit D	19320864	P-1561-D No Heat	11/15/2021	1	APPR	11/16/2021
1611 Pennsylvania Avenue Unit A	19319466	P-1611-A CO detector end of life, replace	11/15/2021	2	APPR	11/15/2021
1611 Pennsylvania Avenue Unit B	19320854	P-1611-B CO detector end of life, replace	11/15/2021	2	APPR	11/15/2021
1710 Delaware Avenue Unit B	19319463	D-1710-B CO detector end of life, replace	11/15/2021	2	APPR	11/15/2021
1710 Delaware Avenue Unit D	19319458	D-1710-D CO detector end of life, replace	11/15/2021	2	APPR	11/15/2021
1710 Delaware Avenue Unit D	19319132	CO detector end of life, replace	11/15/2021	2	APPR	11/15/2021
1720 Delaware Avenue Unit D	19319654	D-1720-D CO detector end of life, replace	11/15/2021	2	APPR	11/15/2021
1741 Pennsylvania Avenue Unit B	19319897	P-1741-B CO detector end of life, replace	11/15/2021	2	APPR	11/15/2021
1741 Pennsylvania Avenue Unit B	19320188	P-1741-B fire extinguisher end of life, replace	11/15/2021	2	APPR	11/15/2021
1750 Pennsylvania Avenue Unit A	19319657	P-1750-A CO detector end of life, replace	11/15/2021	2	APPR	11/15/2021
1754 Pennsylvania Avenue Unit A	19320527	P-1754-A CO detector end of life	11/15/2021	2	APPR	11/15/2021
1826 Pennsylvania Avenue Unit B	19320903	P-1826-B Raccons, pest services request	11/15/2021	2	APPR	11/15/2021
CAPTAINS QUARTERS	19318330	Quarters "A" - No Heat - Approx. 4-5 radiators are not working	11/15/2021	1	APPR	11/15/2021
CAPTAINS QUARTERS	19318327	Quarters "A" - Request replacement of water and air filter for	11/15/2021	3	APPR	11/15/2021
1561 Pennsylvania Avenue Unit E	19333113	P-1561-E Pull wire on outside of back yard gate is broken	11/16/2021	3	APPR	11/17/2021
1750 Delaware Avenue Unit D	19332125	D-1750-D Discoloration on vanity doors	11/16/2021	4	APPR	11/16/2021

HOUSING MAINTENANCE SHOP (SELF HELP)	19332073	HSG Maint Procure Combo Detectors	11/16/2021	3	APPR	11/16/2021
1421 Pennsylvania Avenue Unit A	19333475	P-1421-A Dryer vent may have build up in line	11/17/2021	2	APPR	11/17/2021
1540 Delaware Avenue Unit D	19333476	D-1540-D Front storm door handle latch is broken	11/17/2021	4	APPR	11/17/2021